


2013 Chevrolet Colorado

Submodel: | Engine Type: | Liters:

Fuel Delivery: | Fuel:



Torque Converter Housing with Fluid Pump Removal

Callout

Component Name

Caution: The valve body assembly must be removed prior to removing the torque converter (with fluid pump) housing assembly. Failure to ensure this will cause severe damage to both fluid pump seal assemblies. Also, the load of the valve body pushing on the seals, which in turn push on the pump, may prevent proper pump installation into the case. Refer to control valve body assembly removal.

- | | |
|---|---|
| 1 | Turbine Shaft (O-ring) Seal |
| | Bolt |
| | Note: |
| 2 | <ul style="list-style-type: none">• 6L50 Bolt M8 x 1.25 x 50 (Qty: 8)• 6L80 Bolt M10 x 1.5 x 50 (Qty: 9) |
| 3 | Torque Converter (With Fluid Pump) Housing Assembly |
| 4 | Fluid Pump Seal |