

Last Modified: 12-21-2017	6.8:8.0.48	Doc ID: RM100000000T2Y0
Model Year Start: 2016	Model: LX570	Prod Date Range: [09/2015 -]
Title: AE80F AUTOMATIC TRANSMISSION / TRANSAXLE: COMBINATION SWITCH: REMOVAL; 2016 - 2018 MY LX570 [09/2015 -]		

REMOVAL

PROCEDURE

1. REMOVE UPPER CONSOLE PANEL SUB-ASSEMBLY

(See page [INFO](#))

2. REMOVE INTEGRATION CONTROL AND PANEL ASSEMBLY

(See page [INFO](#))



transmissionmanuals.com