

Last Modified: 12-21-2017	6.8:8.0.48	Doc ID: RM100000000T2WE
Model Year Start: 2016	Model: LX570	Prod Date Range: [09/2015 -]
Title: AE80F AUTOMATIC TRANSMISSION / TRANSAXLE: TCM: REMOVAL; 2016 - 2018 MY LX570 [09/2015 -]		

REMOVAL

PROCEDURE

1. REMOVE COWL SIDE JUNCTION BLOCK RH

(See page [INFO](#))

2. REMOVE TCM

(a) Remove the 2 nuts and TCM from the cowl side junction block RH.

